



Station Information:			
Station	Easting (m)	Northing (m)	Level (m)

GH1	426631.198	328473.810	46.227
GH2	426600.747	328488.870	46.350
GH3	426615.037	328517.110	46.886

OS Note:
Some services may have been omitted due to parked vehicles. The Ordinance Survey file is to be used as a guide only.

OS Buildings	Surveyed Buildings
The Survey has been conducted in the following Survey OS (National Grid and OSGB36) to the Civilian Navigational Sheet Systems (OSGB) and the OS Active Network (OS Net). A true OSGB36 coordinate has been established near to the site corner via a transformation using the OS IN1608 & OS IN1609. The survey has been conducted to this point and a further one or more OSGB36 (15) points established to create a true OS datum for angle orientation. No scale factor has been applied to the survey therefore the coordinates shown are arbitrary & true OS Coordinates please refer to Survey Station Table to enable establishment of the on-site grid and datum.	

[illegible]

New	Date	Description	Drawn	A. Ref.
☐		Topographical Surveys	☐	
☐		Site Engineering	☐	
☐		Utility / GCN Surveys	☐	
☐		Measured Building Surveys	☐	
☐		3D Laser Scanning	☐	
☐		Rent & BHM Records	☐	

Duffield Road
Little Eaton
Derby
DE21 5DR
Tel (01332) 830044
Fax (01332) 830055

St Albans Unit 6, The Courtyard Alban Park St Albans Herts SG1 1DA t. (01727) 854861	Newcastle 24 Rafter Studios Arenberg's Road Newcastle, Co. Down BT5 1YU t. (01912) 736391	Poland ul. Popowicka 91 4b-761 Katowice Poland t. 0048 32 202 2292 www.greenhatch.pl
---	--	--

Roland Moseley

**Rye Close Farm,
Duck Street,
Eggington, DE65 6HG**

Topographical Survey

A1@1:200	15.10.17
----------	----------

MR	GH1718
----	--------

Grid orientation	See note
------------------	----------

Job number	28422
Drawing No.	28422_T Rev. 0

Comments

This plan should only be used for its original purpose. Greenhatch Group accepts no responsibility for this plan if supplied to any party other than the original client.

All dimensions should be checked on site prior to design and construction.

Damage information (where applicable) has been visually inspected from the surface and therefore should be treated as approximate only.

Notes: