




Datum: 30.00m.
Elevation 1.





Datum: 30.00m.
Elevation 2.

Datum: 30.00m.
Elevation 3.

Datum: 30.00m.
Elevation 4.



Datum: 30.00m.
Elevation 1a.



Datum: 30.00m.
Elevation 3a.

OS Note:
The Ordnance Survey tile is to be used as a guide only.
OS Buildings  Surveyed Buildings 
This survey has been orientated to the Ordnance Survey (O.S.) National Grid OSGB36 (15) via Global Navigational Satellite Systems (GNSS) and the O.S. Active Network (OS Net).

A true OSGB36 coordinate has been established near to the site centre via a transformation using the OSTN15GB & OSGM15GB transformation models.
The survey has been correlated to this point and a further one or more OSGB36 (15) points established to create a true O.S. bearing for angle orientation.

No scale factor has been applied to the survey therefore the coordinates shown are arbitrary & not true O.S. Coordinates which have a scale factor applied.

Please refer to Survey Station Table to enable establishment of the on-site grid.

Building Survey Legend:

Sht: 1.00 Hht: 2.12	Sill Height from FFL Head Height from FFL
SL: 51.03m HL: 52.82m	Sill Level from defined datum. Head Level from defined datum.
Susp. Cht: 2.00 Struct. Cht: 3.00	Suspended Ceiling Height from FFL. Structural Ceiling Height from FFL.
Susp. Ceil: 30.00m Struct. Ceil: 31.00m	Suspended Ceiling Level from datum. Structural Ceiling Level from datum.
IFL: 100.00m +100.00m	Internal Floor Level (General). Internal Floor Level (Specific).
 Insertion Point	Insertion Point for overlay drawings of other floors or details.
Incoming Services	
 Elec.	 Gas
 Water	

Topographical Survey Legend:

 Building	 Contour line	 Drainage	 Spot height
 Area line	 Tarmac edge	 Gully	 Rubbish bin
 Line marking	 Bank gully	 Down pipe	 Vest pipe
 Down pipe	 Down pipe	 Ground light	 Ground light
 Caravan	 Verge	 Pipe above ground	 Letter box
 Station and Name	 Water level	 Manhole	 Ladder
 Station Level	 Flag	 Flag	 Flag
 Tree (Bush) / Sapling	 Lamp post	 Lamp post	 Lamp post
 Area of Undergrowth	 Electricity post	 Telephone	 Telephone
 Woodland	 Traffic light	 Binoculars	 Binoculars
 Ridge Level	 Bus stop	 Electric	 Electric
 Ramp Level	 Stop sign	 Stop sign	 Stop sign
 Flat Roof Level	 Stop sign	 Stop sign	 Stop sign
 Gate	 Earth rod	 Tackle	 Tackle
 Water meter	 Gas valve	 Gas valve	 Gas valve
 Intercom	 Air valve	 Cover	 Cover
 Wire Mesh	 Underfloor inspection	 Inspection chamber	 Inspection chamber
 Pipe & Rail	 Rail	 Rail	 Rail
 Rail	 Rail	 Rail	 Rail
 Chain Link	 Bathrooms	 Toilets	 Toilets
 CCTV	 Cable tv	 Cable tv	 Cable tv
 Wooden Panels	 Marker post	 Marker post	 Marker post
 Concrete Panels	 Gas marker post	 Tree Stump	 Tree Stump
 Steel Palisade	 Scaffolding	 Scaffolding	 Scaffolding

Rev	Date	Description	Drawn	O. Ref.
-----	------	-------------	-------	---------



☐ Topographical Surveys
☐ Site Engineering
☐ Utility / CCTV Surveys
☐ Bathymetric Surveys

☐ Measured Building Surveys
☐ 3D Laser Scanning
☐ 3D Revit & BIM Models
☐ Area, Lease & Fire Plans

Rowan House
Duffield Road
Little Eaton
DE21 5DR
Tel (01332) 830044 Fax (01332) 830055
admin@greenhatch-group.co.uk
www.greenhatch-group.co.uk

St Albans Unit 6, The Courtyard Alban Park St Albans Hertfordshire AL4 0LA t. (01727) 854481	Newcastle 24 Riverside Studios Amethyst Road Newcastle Bus Park Newcastle-U-Tyne NE4 7PL t. (01912) 736391	Central London 27 Cornwall Terrace Mess Regents Park London NW1 5LL t. (0207) 2241806
--	--	--

CLIENT

Scott and Anna
Mulligan-Freeman

PROJECT

4 Main Street
Ambaston
DE72 3ES

TITLE

Existing
Elevations

SCALE A2@ 1: 200	DATE 23.04.20
DRAWN SL	QUALITY REF GH7317

Level datum Grid orientation	See OS notes above See OS notes above
Job number 36637	

Drawing No. 36637_02_E	Rev. 0
----------------------------------	------------------

Comments:
This plan should only be used for its original purpose. Greenhatch Group accepts no responsibility for this plan if supplied to any party other than the original client.
All dimensions should be checked on site prior to design and construction.
Some services may have been omitted due to parked vehicles.
Drainage information (where applicable) has been visually inspected from the surface and therefore should be treated as approximate only.
Notes: